



**BRACKETRY SYSTEMS, INC.**

8785 Harmon Road  
Fort Worth, TX 76177  
817-232-8199  
[www.bracketrysystems.com](http://www.bracketrysystems.com)

**Service Bulletin # FO-3**

**Subject: Ford E Series**

**Date: 3-6-2015**

**Author: Jana Burns**

**Kit(s) Affected: 26068C**

**Kit Description: 2015-2013 Ford E Series 5.4 or 6.8 Ltr**

**It has come to our attention that, in some cases, the engine placement is at the maximum forward tolerance in the engine cavity, and this causes the potential for the grommets on the face of the compressor clutch to hit the airbox. We have added a 20068-4 aluminum rail to our kit to space the airbox to ensure there is proper clearance.**

**SERVICE BULLETIN**