



**BRACKETRY SYSTEMS, INC.**

8785 Harmon Road  
Fort Worth, TX 76177  
817-232-8199  
www.bracketrysystems.com

**Service Bulletin # RA-1**

**Date:** 6-1-2015

**Subject:** 1954-3 and 1954-5 Shroud Braces

**Author:** Jana Burns

**Kit(s) Affected:** 1954-16, 1954-21, 1954-216, 1954-221

**Kit Description:** 2015-13 RAM 5500HD 6.7 Liter Cummins

BSI made a kit change to the 1954 series of kits in which we removed the 1954-3 shroud brace and replaced it with the 1954-5 shroud brace. This change was made to prevent the transmission cooler line from hitting the knobs on the face of the compressor clutch.

All new installs should have the 1954-5 shroud brace in the kit. For all previous installs, if the kit is updated for any reason you must use the 1954-5 shroud brace; do not reuse the 1954-3 shroud brace.

**SERVICE BULLETIN**